

# INDUSTRIAL

# STRIP-IT

## *Rinse Free Stripper*

**S**TRIP-IT is a labor saving, very aggressive rinse free floor stripper. Strip-It is designed to be used to remove any floor finish including floors with excessive build-up and floors that have been buffed or burnished with ultra high-speed machines. Strip-It will not leave an alkaline residue, therefore no rinsing or neutralizing is required before recoating.

### **USE ON**

- Resilient Floors
- Terrazzo
- Marble
- Slate
- Quarry Tile
- Concrete

### **USE IN**

- Schools
- Hospitals
- Churches
- Country Clubs
- Restaurants
- Hotels/Motels

### **WHY USE**

- Labor Saving
- Powerful
- Versatile
- No Film
- No Rinse
- No Neutralizing

### **DIRECTIONS FOR USE**

1. Dilute this aggressive fast stripper accordingly with hot water:

**Normal stripping:** 1 part to 10 parts water.

**Aggressive stripping:** 1 part to 5 parts water (necessary if floors have been burnished or high-speed buffed).

2. Apply liberally with mop or automatic scrubber to floor. Be sure to leave surface very wet!

3. Allow to remain 3-4 minutes and remop. This provides slight agitation necessary for 100% removal of old floor finish. Allow another 3 minutes before vacuuming

4. Pickup solution using a wet vac. If any finish remains (such as around baseboards), use a bowl swab and DILUTED liquefier solution to touch up.

5. Allow floor to dry. No rinsing is necessary if surface appears free of dust after drying.

6. Recoat.

**NOTE:** In order to determine use-dilution, pretest on a small area. Strip only a manageable area at one time. Although pickup using a wet vac is advised, the stripper/finish may be mopped-off of the floor.

**P E R F O R M**  
M A N U F A C T U R I N G

**Kansas City, KS. - 800-423-9861**

***Products That Perform!***